



## НЕОБХОДИМЫЕ ИНСТРУМЕНТЫ



## СПИСОК ДЕТАЛЕЙ

X2	X2	X2	X4	X4	X4	X4
X8	X2	X2	X4	X2	X2	X8
4X30	X16	4X10	X8	4X12	X4	ф3.2

1

РАЗМЕРЫ	A (мм)	B (мм)
800X800	785-800	785-800
900X900	885-900	885-900
1000X1000	985-1000	985-1000

2

3

4

5

6

